

Conveyor Belt Repair

Repair: Complex edge repair with exposed steel cable

Material: Rapid Repair (2 hour cure time)

Situation:

A material loading facility required an edge repair to be completed to a damaged conveyor belt that had been cut away and had left the steel cable exposed. The repair was 10 metres in length and required the edge to be built out 20mm and encase the steel cable.

Result:

We were able to fully repair the belt by building out the edge across the 10-metre section and encasing the steel cable into the repair.

The repair was completed saving time and considerable cost and the belt was available for use at the completion of the shut down. There have been no issues with the repairs following the belt returning to full service.



Above - damage to the edge exposing cable



Right – repair completed

For more information on any of our products or services, please contact either our Newcastle or Sydney offices on:

T: + 61 400 386 239 or + 61 414 248 855

www.cobond.com.au