

Conveyor Belt Repair

Repair: Edge damage – fabric belt

Material: Qik Fix Conveyor Repair

Situation:

A power station required an edge of the conveyor belt to be rebuilt after only having installed the belt for 6 months. The repair was 60 metres in length and required the edge to be rebuilt as a result to alleviate the 'shark bite' effect.

Result:

We were able to fully rebuild the edge and encase and protect the fabric from moisture.

The repair was completed saving time and considerable cost and the belt was available for use at the completion of the shut down. There have been no issues with the repairs following the belt returning to full service.



The edge damage to the fabric belt



The edge has been rebuilt

For more information on any of our products or services, please contact either our Newcastle or Sydney offices on:

T: + 61 400 386 239 or + 61 414 248 855

www.cobond.com.au