

## Conveyor Belt Repair

**Repair:** 120-metre skirt damage conveyor belt repair

**Material:** Qik Fix (30 minute cure time)

**Situation:**

The re-claimer boom conveyor belt had a damaged section that ran along the entire 120-metre length of the belt. The repair was required because a large rock was caught between the skirt and the conveyor belt and had worn away a 100mm (W) x 12mm (D) deep groove in the belt.

**Result:**

Rather than changing out the belt at considerable cost, the belt was repaired at a fraction of the replacement cost – see image below.

There have been no issues with the repairs following the belt returning to full service.



For more information on any of our products or services, please contact either our Newcastle or Sydney offices on:

T: + 61 400 386 239 or + 61 414 248 855

[www.cobond.com.au](http://www.cobond.com.au)