

Conveyor Belt Edge Repair

Repair: 96-metre skirt damage conveyor belt repair

Material: Rapid Repair (2 hour cure time)

Situation:

The conveyor belt had a worn out section that ran along the entire 96-metre length of the belt. The repair was required as a result of the hard skirt wearing away a 100mm (W) x 15mm (D) groove into the belt.

Result:

Rather than changing out the belt at considerable cost, the belt was repaired at a fraction of the replacement cost of the belt.

This repair required three stages to complete. At the end of each stage, the belt was available for use at the completion of the shutdown.

There have been no issues with the repairs following the belt returning to full service.



Damage to the belt from the skirt.



Repair completed.

For more information on any of our products or services, please contact either our Newcastle or Sydney offices on:

T: + 61 400 386 239 or + 61 414 248 855

www.cobond.com.au