

Conveyor Belt Repair

Repair: **Reseal edge – fabric belt**

Material: **Edge Sealant (6 hour cure time)**

Situation:

Our customer required the edge of the conveyor belt to be resealed because the 2mm protective rubber edge had been removed from the edge of the conveyor belt.

The repair was required so as to prevent moisture from penetrating the fabric and delaminating the rubber. This repair was 700 metres in length and required the exposed fabric to be resealed.

Result:

We were able to reseal the entire edge and protect the fabric from moisture. The repair was completed saving time and considerable cost and the belt was available for use at the completion of the shut down. There have been no issues with the repairs following the belt returning to full service.



The edge damage to the fabric belt



The edge has been resealed

For more information on any of our products or services, please contact either our Newcastle or Sydney offices on:

T: + 61 400 386 239 or + 61 414 248 855

www.cobond.com.au