## **Conveyor Belt Repair**

Repair: Splice damage conveyor belt repair

Material: Qik Fix (30 minute cure time)

## Situation

The conveyor belt on the crusher had torn at the splice joint, bringing the machinery and earthmoving to a stand still. Rather than replace the belt, we were asked to repair the belt so they could use it for another three months of production.

## Result:

Rather than changing out the belt at considerable cost, the belt was successfully repaired for less than 10% of the replacement cost of a new belt.

There have been no issues with the repairs following the belt returning to full service and it has outlasted the life of the belt.



Splice joint repair primed



Repair completed.

