Conveyor Belt Repair

Repair: Spot / Puncture Repairs

Material: Rapid Repair (2 hour cure time)

Situation:


A material loading facility required had 40 spot repairs to the boom conveyor as a result of material being caught in between the pulley and the conveyor belt.

Result:

The repair was completed saving time and considerable cost and the belt was available for use at the completion of the shut down. There have been no issues with the repairs following the belt returning to full service.



An example of the spot repair (primed)



Repair completed

For more information on any of our products or services, please contact either our Newcastle or Sydney offices on: **T:** + 61 400 386 239 or + 61 414 248 855 **www.cobond.com.au**

