

Conveyor Belt Repair

Repair: 14-metre edge damage to conveyor belt repair

Material: Rapid Repair (2 hour cure time)

Situation:

The conveyor belt had drifted causing considerable damage to the edge of the belt. The repair was required so as to avoid the edge tearing away and potential ripping out the cable.

Result:

Rather than risk the edge tearing away and ripping out the cable and then having to replace the entire belt - \$500K, we undertook to repair the edge to build strength back into it and thus protecting the cable.

There have been no issues with the repairs following the belt returning to full service.



Edge to be repaired



Edge repaired

For more information on any of our products or services, please contact either our Newcastle or Sydney offices on:

T: + 61 400 386 239 or + 61 414 248 855

www.cobond.com.au